

Subject: 10T83479 - 2015 36Y Vista


From: Winnebago Industries Service Administration <or@winnebagoind.com>

Date: 1/10/2017 1:07 PM

To: "swharton08@gmail.com" <swharton08@gmail.com>

Sue,

There will be 2 pieces of foam under the grey tank. Please look at the picture below for where the foam would be located. The foam is in red on the grey tank.



Thank you,
Nicholas

WINNEBAGO[®]

Nicholas Fure | Service Advisor | 800-537-1885
605 W Crystal Lake Rd | Forest City, IA 50436

Thank you for being a customer!

-----Original Message-----

From: Susan Wharton [mailto:swharton08@gmail.com]

Sent: Monday, January 9, 2017 10:59 AM

To: Winnebago Industries Service Administration <or@winnebagoind.com>

Subject: 10T83479- 2015 36Y Vista

We have had a gray water leak for several months. A question we have is how many pieces of foam should be under the gray water tank.

Thanks

Sue and

This electronic transmission and any documents accompanying this electronic transmission contain confidential information belonging to the sender. This information may be legally privileged. The information is intended only for the use of the individual or entity named above. If you are not the intended recipient, you are hereby notified that any disclosure, copying, distribution, or the taking of any action in reliance on or regarding the contents of this electronically transmitted information is strictly prohibited.